



Alternative 2 – Design Options

Alternative 2 Option	Cheerwine Distribution Plant	Tyner Rd./Tyner Loop Rd.	Farmer's Market	Endicott Rd.
Option a	Access moved to Tyner Loop Rd.	Full access provided on southern leg. Northern leg closed.	Entrance moved north to meet realigned Endicott Rd.	Realigned south. Full access.
Option b	Access moved to Tyner Loop Rd.	Full access provided on northern leg. Southern leg closed.	Entrance moved north to meet existing Endicott Rd.	Not realigned. Full access.
Option c	Access moved directly across from Farmer's Market entrance.	Full access provided on southern leg. Northern leg closed.	Entrance location unchanged.	Not realigned. Full access.